Name	5 SE				Date	6-15-	15	Page	/ of /	1
Vatc	(Please hman ted From	•	يقا				W.O Numbe			9.
	Exception Chair		- Daniel Commission of the Com		Rail	Switch	Cod	es l	Status	Repair
tem	From	То	Number		E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				•						
2. 3.										
4.										
-										
5.										
6.										
7.			ECTROCOPHENDATES							
8.										
9. m	COMMENTS	L				L				
	NO N	EW T	DEFECT	5	NOT	ED IN	ARE			
						±3				
								2		
	Mana Curita	h i- the ere	a of Ingress	- /v	31/15	UAL ONLY N				
W 	ere all single of NONO	perating me		necting	rod type s			eratated in	each posit	lon ?
Re	ason for spec	cial Inspec	tion ?					ii	····	_
Tra	ck Inspector S.	lgnature		×		···	Supervisor	y Cretifica	ition///	Suff 5-15

	(6					4	1 BC #			
Vame	W. Bri	Yan t			Date C	6-15-	15	Page	l of	<u>C</u>
1	/ Diagon	Defeat)						191	220	7,
	hman <u>N A</u>	1. 11	. 41 =	_ (V-1-0-	phing	W.O Numbe	er 170	250	_
nspec	ted From	- G ther (2111	10	2010 5	PHINS		ā		
	Exception Chain	Marker No.	w.o.	Track	Rall	Switch	Cod	es	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1				•						
2.		•								
3.		787					X			
4.										
	Tig.									
5.	***		建工品制度							
3.										
7.										
В.										
Э.										
m	COMMENTS									
)—									*	
	6							92		
s	ere all single on	erating med	ON Yes_	necting r	od type s	witches inside	area and ope		each positi	ion ?"
Rea	ason for spec	ial Inspec	tion ?						., 1	0,
	ck Inspector SI		-	×		ž	Supervisor	y Cretifica	tion (1)	16-
į.										

Name		ZHISLEP),		Date	6/16/15		Page	of)	52
,	(Please hman ted From CAA	Print) ΔΕΛ	·	то Д	JNTH	ICUH	W.O Numb	er 196	1768	1.4
	Exception Chair	n Marker No	w.o	Track	Rall	Cultab	T			
Item	From	To	Number	No.	E/W	Switch No.	Comp		Status	Repair
1.				. 110,		140.	Comp.	Defect	S/Y/R	Y/N
2.	30						-			
3.		9						 		-
4.			Market Branch							
5.	•								=3	
в.										
7.			国际制度制度							
8.			如思想经过常使的语言	- 1						
9.										
em	COMMENTS									
-	RIDING	INSPEC	TIDA	-						
-	NO NEW D	EFFCTS	NOTED IN	AREA						
-										
\dashv										
\dashv										
\rightarrow										
$\overline{}$										
+										
\dashv										
-+							·			
-							30	(. */)		
	144 0 . 14 . 1	1 44			VISIO	Charles and the same of the sa				
14/-	Were Switch	in the area	of Inspected	Ye	S_VISUA	× 0409 N	0			
s	re all single ope NO_X	erating mec	nanism & con	ecting re	od type s	switches inside	area and ope	eratated in e	each position	on ?
	SPECIAL IN	SPECTIO	N Yes	1	NOX					
Rea	son for specia	al Inspect	ion ?)	100	_
									6) f
Traci	k Inspector Sig	ınature					Supervisory	Crotificati	on with	1
	TSches						Super visory	Credificati	OIL PALLY	14/
/	Schis	lin				¥		÷ 34	16	16
ī										
Į.										
		<u>@</u>								

Name	5 5E (Please)				Date &	6-16-1	5	Page	of	
.√atcl	•		2.ING	То	Camo	EN Yprï	W.O Numbo	er <u>/96</u>	2327	/*
	Exception Chain	Marker No.	W.O.	Track	Rail	Switch	Cod		Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	, , J., , ,		建筑建筑 建	,		4				
2.		2								
3.		3	海山東河東部							
4.	~~~		a all substants							
5.									⊋%	
6.			Shirt Balls							.,
7.		F-12	CONTROL DE LA CO							
8.										
9.			HIROMAN DIM							
em	COMMENTS		DATE PROPERTY OF THE PROPERTY	3						
	RIDING	TN	SPECTO	n		76.				
	NO NE	(1)	EFFCTS	NIC	TED	IN A	REA			
\dashv										721
	Were Switch	n in the are	a of Inspecte	ed (Ý	es VISL	LALONCYN	0			
W	ere all single op		•					eratated in	each posit	ion?
9 s	NO /	•			- •		·		•	<u>}</u>
	SPECIAL IN	ISPECTION	ON Yes_		NO_ <u>i</u>					
Rea	ason for spec	ial Inspec	tion ?					1		
									4//	C. I
	ck Inspector SI	_					Supervisor	ry Cretifica	tion///	suffe-
'n	Stan &	eu				*(Va	16-

))0	ell			Date /	-16-19	5	Page	of	
200	(Please	Print)								
Vatc	hman				~		W.O Numbe	or 1968	2327	/ 4
spec	ted From	MT ROY	1nc	То	PENI	V STATT	oN	(# ⁰		
	Exception Chai	n Marker No.	W.O.	Track	Rall	Switch	Cod	es	Status	Repair
tem	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				•						
2.										
3.										
1 .										
_			建设建设建筑						2	
5.										
3.			医内侧侧侧							,
7.			设施控制限制设置							
3.										
9.	<u>×</u>		克里伊斯里特				-			
n	COMMENTS		VSPECT.							
	ev.		31							
S	Were Switch ere all single on NO SPECIAL IN ason for speci	perating med	N Yes	ecting re	od type sv	_	area and ope		each positio	on ?

Name	SSEL				Date	6-17-15	~	Page	of	- 1
IVAIIIO	(Please				Date	0 11				
Vatc	hman				<i>p</i>	,	W.O Numbe	r_196	1771	<u>/ </u>
Inspec	ted From	LINATICE	KM)	To	BW	/				i
			Intrinspose and the second					<u></u>		
	Exception Chain			Track	Rall	Switch	Cod		Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.	39									
3.		*	(88)			ļ	8			
4.			A Part of the last							
						ļ				
5.										
6.						ļ				
7.			personal property of the second secon							
8.										
9.			共同种种规范							
em	COMMENTS			,						
\dashv	RIDING		ECTION				A			
\dashv	NO NEI	N DE	FECTS	NO	TED	IN A	CE A			
_										
_										
_										
_										
	**							(4)		
					2 7					
	Were Switch	h in the are	a of Inspecte	ed (Ý	res VIS	HALOWLY NO	0			
W	ere all single op	erating med	hanism & co	necting	rod type	switches inside	area and op	eratated in	each posit	lon ?
	NO\/									95
	SPECIAL IN	ISPECTIO	ON Yes		NO.					
					8					
Re	ason for spec	ial Inspec	tion?							
. ,5										
									/	V
Tra	ck Inspector Si	anatura					Supervisor	v Cretifica	tion // S	Stephe
iid		griature				77	Cuper visor	, Oromica		JU TU
	XA X	e ex				•#				. /
2	18m 13									7-16-
1									1 6	, , -

Name	SSEL	C			Date	6-17-1	5	Page	of	
Vatc	(Please F nman		m	То	Cro	mvell	W.O Numb	er <u> 196</u> ,	1771	/ 4
-	Exception Chain	Marker No.	wa	Track	Rall	Switch	Cod	les I	Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	1,0111		THE PROPERTY.	10						
2.			EAST TO LET WATER							
3.		Æ	编译的概念							
4.										
				N						
5.									int.	
6.		×								
7.			e roughthamanas						180	
8.										
9.										
)										
	Were Switch ere all single op NO SPECIAL IN	erating med	chanism & co	necting	rod type			peratated in	each posit	ion ?
Re	ason for spec	ial Inspec	tion ?	*					e 1 A	P. 1
Tra	ck Inspector SI	gnature		*			Superviso	ry Cretifica	ation M	16 -

nspec	hman ted From Huאו						MA O North	19/	38E	, 4
	1.0101	VALLEY	-	То	LUTHE	MILE	- vv.O Numb	er <u> 116</u>	2300	/ _
	Exception Chair	Marker No.	W.O.	Track	Rail	Switch	Cod	es	Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.			(周報) 開展失政	•						
2.										
3.			海路 中原。							
4.										
	340									
5.									199	
6.			巴西斯斯 斯斯							.9
7.			国基础基础的高级							
8.										
9.										
em	COMMENTS									
	RIDING	INSPE	CTION							71
)	*		ř.							
	21				(#)			Ç.		
W∈ ∋ s	Were Switch ere all single op NO_X		a of Inspected hanism & con		od type sv		oarea and ope	eratated in o	each position	on ?
	SPECIAL IN	ISPECTIC	N Yes	1	NO					
Rea	son for spec	ial Inspect	ion ?						-	
Trac	k Inspector SI	gnature		9.0	*:		Supervisory	/ Cretificat	ion <u>MS</u>	yk

Name		ISLER	n n		Date	6/18/15		Page	/ of 2	<u>.</u>
	(Please									
		RYANT		_	2		W.O Numb	er	00319	/-
ınspec	ted From CAM	OFA)	•	То (gen Jr	PING	-	a a		
	Exception Chair		W.O.	Track	Rail	Switch	Coc	les	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.			NAME OF TAXABLE							
									.0	
5.			10世紀68日本						(appli	
6.			。但是他们是 是1							
7			近極性制度制度的							
8.										
9,	2									
Item	COMMENTS									**************************************
	WO A	VAU DEL	EECTS NOT	TED IN	ARE	4				
					7,11					
\LL										
									•	
										-
	60									
-	***************************************									
	More Curital	h in 4h a a								
١٨/،			of Inspected				o			
es	ere all single op	erating meci	nanism & con	ecting re	od type s	switches inside	area and ope	eratated in	each positi	on ?
es	NO_ <u>_</u>									29
	SPECIAL IN	ISPECTIO	N Yes	1	40 <u>~</u>					
Rea	ison for spec	ial Inspecti	ion ?							
									3.1	7
										9
Trac	k Inspector Sig	gnature		,			Supervisory	Cretificat	ion MX	Auth
	T Sche			•			- upo. v.co.,	O. O. I. II. O. I.		
	1 this	<u>~</u>				*			97	/ "
									UL	-19-15

Exception Chain Marker No. W.O. Track Rall Switch Codes Status Retem From To Number No. EW No. Comp. Defect S/Y/R Y 1. 2. 3. 4. 5. 6. 6. 7. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8.	191 0210	Date @			SCHISLER ase Print) BRYANT	(Plea	Matal
Exception Chain Marker No. W.O. Track Rail Switch Codes Status Reset From To Number No. EW No. Comp. Defect S/Y/R Y No. C	W.O Number_ / 1603/9		To		PENIN LINE	ed From	
Exception Chain Marker No. W.O. Track Rail Switch Codes Status Reference From To Number No. E/W No. Comp. Defect S/Y/R Y			10 E	•	y END CAL	od i ioiii	юросі
Item		Rall	Track	w.o.	hain Marker No.	Exception C	
1. 2. 3. 4. 4. 5. 6. 6. 7. 8. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9.	1100						Item
2. 3. 4. 5. 6. 7. 8. 9. COMMENTS Were Switch in the area of Inspected Yes_Y NO Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNO_X Reason for special Inspection? Track Inspector Signature Supervisory Cretification Manual Supervisory Cr	Solida Siliki (ii)						1.
Were Switch in the area of Inspected Yes_Y NO_ Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION Yes_NO_X Reason for special Inspection? Track Inspector Signature Supervisory Cretification						¥0:	2.
5. 6. 7. 8. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9.				(integral part)			3.
Were Switch in the area of Inspected Yes_Y NO_ Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION Yes NO_X Reason for special inspection? Track Inspector Signature Supervisory Cretification							4.
Were Switch in the area of Inspected Yes_Y NO_ Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION Yes NO_X Reason for special inspection? Track Inspector Signature Supervisory Cretification					11		
Were Switch in the area of Inspected Yes_Y NO_ Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNO_X Reason for special Inspection? Track Inspector Signature Supervisory Cretification							5.
Were Switch in the area of Inspected Yes_YNO_ Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNO_X Reason for special Inspection? Track Inspector Signature Supervisory Cretification							6.
SPECIAL INSPECTION Yes NO SPECIAL Inspection? Were Switch in the area of Inspected Yes Y NO Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION Yes NO X Reason for special Inspection? Track Inspector Signature Supervisory Cretification When				科科教科科的教教			7.
Were Switch in the area of Inspected Yes X NO_ Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION Yes NO_X Reason for special Inspection? Track Inspector Signature Supervisory Cretification							8.
Were Switch in the area of Inspected YesXNO Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							9.
Were Switch in the area of Inspected YesXNO Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification					S	COMMENTS	em
Were Switch in the area of Inspected YesX NO Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION Yes NOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification		ADEA	TEA 141	CECTS NOT	NEU DE	Ma	
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification		11.2.2.11	<u>uu 7-0</u>				
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							\rightarrow
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							-
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							-+
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							\rightarrow
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification)—
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							_
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification							
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification	ni.					h	
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification					1174		
Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? SPECIAL INSPECTION YesNOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification		- 14	J Va	of languages	itch in the area	Ware Swi	
SPECIAL INSPECTION Yes NOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification				•			14/0
SPECIAL INSPECTION Yes NOX Reason for special Inspection? Track Inspector Signature Supervisory Cretification	switches inside area and operatated in each position?	oa type swit	ecting ro	anism & con	operating meci	we all single	VV 6
Reason for special Inspection? Track Inspector Signature Supervisory Cretification	.05				_	NO_/	8
Reason for special Inspection? Track Inspector Signature Supervisory Cretification						00=0111	
Track Inspector Signature Supervisory Cretification Miles	<u> </u>	10 <u>X</u>	N	N Yes	INSPECTIO	SPECIAL	
Track Inspector Signature Supervisory Cretification Miles							
Track Inspector Signature Supervisory Cretification Miles				on ?	ecial Inspecti	son for spe	Rea
	Supervisory Creditionalism MIKA-H				Slanature	k Inspector	Traci
1 school 6-1	Supervisory Creditication My Mount						
6-1	· Worth	*			hisk	1 sc	
	4						
	7 - 19						
	6-19						

lame	5 56				Date (6-18-	15	Page	of	
Natcl rspect	(Please hman ted From (Print)	1/e	То	Cous	Spring	W.O Numb	er <u>/96</u>	0356	/* <u> </u>
	Exception Cha	n Marker No.	W.O.	Track	Rall	Switch	Coo	les	Status	Repair
tem	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.			1946年新華			ži.				
2.	0000									
3.		a					-			
4.										
-										
5.									1968)	
8.			的复数形式							y
7.			BARTESTEN PER STATE							
3.										
9.		L	[[3]] 计连续控制							
n	COMMENTS	-	COLL	W Al			-			
\dashv	RIDIN		EFECT		NOTE	D IN	AREF			
1								3		
We	Were Switchere all single onNO		a of Inspected hanism & con	d (Ye	od type sv	ALONLY No	O area and ope	eratated in	each positi	on?
	SPECIAL IN	SPECTIC	N Yes	١	VO/	_				
Rea	son for spec	ial Inspect	ion ?					E:		
Trac	k Inspector SI	gnature		×	3		Supervisory	/ Cretificat	tion <u>M</u>	my

Name	SCH	ISLER			Date	6/19/15		Page	l of /	- 1
Vatc	(Please hman W	Print) Bryent					W O North	er_1960		ý.4
	ted From LIN			то С	ROMW	ELI	W.O Numb	er_1 100	319	
			•				•			
	Exception Chall		W.O.	Track	Rall	Switch	Cod	les	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	UH 491435			<u> </u>	W		M 301	323	Y	
2.	· · ·								7	
3.							22			
4.										
_										
5.									160	
6.										
7.			以解理权研制共和							
8.										
9.			(1) [1] [1] [1]							
m	COMMENTS					,				
4	DRAIN COL	IER GRA	TE MISSIA	us, TR	IBBING.	FALLING	HAZARD			
\rightarrow										
_									14	
_										
	- 115									
									*	
_										
	+3								· ·	
_										
	Were Switch	in the area	of Inspecto	d V	s_X	At				
We	ere all single op	eratino mecl	haniem & cor	ecting re	nd type o	NN	o			_8
s	NO X	oraling moor	iainsiii a coi	lecting it	ou type s	wirches luside	area and ope	eratated in (each position	on ?°
										1.5
	SPECIAL IN	SPECTIO	N Von							
	SPECIAL IN	SPECTIO	iv res	r	VOX	<u></u>				
Dog	son for anac	lal laanaati	lan 0							
Rea	son for spec	iai inspecti	юп ?							
										1.
									1.10	0
	k Inspector Sig	gnature		2		4	Supervisory	Cretificat	ion MT	with
	T Sel	(-		,				1	7"
/	1906	u (4,	hr .
									6-	21-19

ame					Date	6/19/15		Page	2 of 2	<u>.</u>
8	(Please									
		BRYANT			_		W.O Numb	er <u> 196</u>	0399	/
nspec	ted From しん	THICUY		To	Bwi		•			
	Exception Chain Marker No.				T 5 "					
Item	From	To	W.O. Number		Rail	Switch	Codes		Status	Repair
1.	FIOR	10	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
2.								-		
3.			Autoria en la compara de la co							
4.										
			Day Bulkson							
5.								 	<u> </u>	
6.										
7.			克斯特里斯特斯						0.	
8.										
9.				4)						
em	COMMENTS		CALIFORNIA ASSESSMENT							
	NO N	Eus DEL	FECTS N	OTEA	INIA	DEN				
				0164	1111	الرحم				
\dashv										
\rightarrow										
-										
-										
)—										
-										
-									· · ·	
\dashv										
	22							**		
	Were Switch	in the area	of Inspecte	d Ye	s X	N	2			
We	ere all single ope					witches inside	area and one	eratated in	anch positi	on 2:
s	NO X				JE 1, pe 0	Witorico mojdo	area and op	sialalou III l	each position	OH Y
	SPECIAL IN	SPECTIO	N Yes		VOX					
	J. 200 (201)	0, 20,,0		'	10 <u>·</u>					
Rea	son for speci	al inenecti	ion 2							
1 (00	iodii idi apedi	ai mapecu								1
										//
7		STANDARD AND BOTH OF THE STANDARD							411	/
Irac	k Inspector Sig	nature				j±	Supervisory	Cretificat	ion M	with
	TSchiol	_				65				//
									T.	/ '
									6	5-21
									<u>a</u>	
1										
)										

Name A. Robette (Please Print) Vatchman Inspected From Candon			То		Vate 6-21-15 Page of W.O Number 196833					
		. 1684	urodunianiana					A.	13	
Mana	Exception Chain Marker		W.O	Track	Rall	Switch	Cod		Status	Repair
item	From To		Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
2.		1990		-						
3.		516								
4.		100				~				
"		1131			-					
5.									- 9	
6.		Thirties and the second								
7.		(i)							,	
8.		10017			— i					
9.										
m	COMMENTS	EN CH	14.1419083964							
	Were Switch in the	area of	- Inspecte	d Ve	95				,	•
s	ere all single operating on the single operating of the single operating o	mechar	Yes	necting re	od type sv	vitches inside	area and ope		each position	on ?
	son for special Insp		າ ?	The Control			Supervisor		tion W.M.	The state of the s
Ch	Tula To			,	×			, erounou	P	6-21